


Chapter 11: Metal Alloys Applications and Processing

ISSUES TO ADDRESS...

- How are metal alloys classified and how are they used?
- What are some of the common fabrication techniques?
- How do properties vary throughout a piece of material that has been quenched, for example?
- How can properties be modified by post heat treatment?



Taxonomy of Metals




Adapted from Fig. 11.1, Callister 7e.

Adapted from Fig. 9.24, Callister 7e. (Fig. 9.24 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



Steels




increasing strength, cost, decreasing ductility


Based on data provided in Tables 11.1(b), 11.2(b), 11.3, and 11.4, Callister 7e.




Refinement of Steel from Ore




heat generation



reduction of iron ore to metal



purification



Ferrous Alloys

Iron containing – Steels - cast irons

Nomenclature AISI & SAE

10xx Plain Carbon Steels

11xx Plain Carbon Steels (resulfurized for machinability)

15xx Mn (10 ~ 20%)

40xx Mo (0.20 ~ 0.30%)

43xx Ni (1.65 - 2.00%), Cr (0.4 - 0.90%), Mo (0.2 - 0.3%)

44xx Mo (0.5%)

where xx is wt% C x 100

example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel -- >11% Cr



Cast Iron


- Ferrous alloys with > 2.1 wt% C
 - more commonly 3 - 4.5 wt% C
- low melting (also brittle) so easiest to cast
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{Fe} (\alpha) + \text{C} (\text{graphite})$$
 - generally a slow process



Fe-C True Equilibrium Diagram

Graphite formation promoted by

- Si > 1 wt%
- slow cooling



Adapted from Fig. 11.2, Callister 7e. (Fig. 11.2 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



Types of Cast Iron

Gray iron


- graphite flakes
- weak & brittle under tension
- stronger under compression
- excellent vibrational dampening
- wear resistant



Adapted from Fig. 11.3(a) & (b), *Callister 7e*.

Ductile iron

- add Mg or Ce
- graphite in nodules not flakes
- matrix often pearlite - better ductility



Types of Cast Iron

White iron


- <1wt% Si so harder but brittle
- more cementite



Adapted from Fig. 11.3(c) & (d), *Callister 7e*.


Malleable iron

- heat treat at 800-900°C
- graphite in rosettes
- more ductile




Production of Cast Iron

Adapted from Fig.11.5,
Callister 7e.




Reheat: hold at
 $\sim 700^{\circ}\text{C}$ for 30 + h

Fast cool	Slow cool
$P + G_r$	$\alpha + G_r$



Pearlitic malleable




Ferritic malleable


Fast cool	Moderate	Slow cool
$P + \text{Fe}_3\text{C}$	$P + G_f$	$\alpha + G_f$



White cast iron




Pearlitic gray cast iron




Ferritic gray cast iron

Moderate	Slow cool
$P + G_n$	$\alpha + G_n$



Pearlitic ductile cast iron



Ferritic ductile cast iron

Limitations of Ferrous Alloys

- 1) Relatively high density
- 2) Relatively low conductivity
- 3) Poor corrosion resistance



Nonferrous Alloys

• Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze: Sn, Al, Si, Ni are subst. impurity (bushings, landing gear)

Cu-Be: precip. hardened for strength

• Ti Alloys

-lower ρ : 4.5g/cm³
vs 7.9 for steel
-reactive at high T
-space applic.

NonFerrous Alloys

• Al Alloys

-lower ρ : 2.7g/cm³
-Cu, Mg, Si, Mn, Zn additions
-solid sol. or precip. strengthened (struct. aircraft parts & packaging)

• Mg Alloys

-very low ρ : 1.7g/cm³
-ignites easily
-aircraft, missiles

• Refractory metals

-high melting T
-Nb, Mo, W, Ta

• Noble metals

-Ag, Au, Pt
-oxid./corr. resistant



Metal Fabrication

- How do we fabricate metals?
 - Blacksmith - hammer (forged)
 - Molding - cast
- Forming Operations
 - Rough stock formed to final shape

Hot working

- T high enough for recrystallization
- Larger deformations

vs.

Cold working

- well below T_m
- work hardening
- smaller deformations




Metal Fabrication Methods - I

FORMING


CASTING

JOINING

- Forging (Hammering; Stamping) (wrenches, crankshafts)




- Drawing (rods, wire, tubing)




die must be well lubricated & clean

- Rolling (Hot or Cold Rolling) (I-beams, rails, sheet & plate)



Adapted from Fig. 11.8, Callister 7e.

- Extrusion (rods, tubing)



ductile metals, e.g. Cu, Al (hot)



Metal Fabrication Methods - II



- **Casting**- mold is filled with metal
 - metal melted in furnace, perhaps alloying elements added. Then **cast** in a mold
 - most common, cheapest method
 - gives good production of shapes
 - weaker products, internal defects
 - good option for brittle materials



Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting

(large parts, e.g.,
auto engine blocks)




- trying to hold something that is hot
- what will withstand $>1600^{\circ}\text{C}$?
- cheap - easy to mold => sand!!!
- pack sand around form (pattern) of desired shape

Metal Fabrication Methods - II



- **Sand Casting**


(large parts, e.g., auto engine blocks)



- **Investment Casting**

(low volume, complex shapes e.g., jewelry, turbine blades)

plaster die formed around wax prototype



Investment Casting

- pattern is made from paraffin.
- mold made by encasing in plaster of paris
- melt the wax & the hollow mold is left
- pour in metal



Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting


(large parts, e.g., auto engine blocks)



- Investment Casting


(low volume, complex shapes e.g., jewelry, turbine blades)

plaster die formed around wax prototype




- Die Casting

(high volume, low T alloys)



- Continuous Casting

(simple slab shapes)




Metal Fabrication Methods - III

FORMING


CASTING

JOINING

- Powder Metallurgy
(materials w/low ductility)



- Welding
(when one large part is impractical)




- Heat affected zone:
(region in which the microstructure has been changed).

Adapted from Fig. 11.9, *Callister 7e*.
(Fig. 11.9 from *Iron Castings Handbook*, C.F. Walton and T.J. Opar (Ed.), 1981.)



Thermal Processing of Metals


Annealing: Heat to T_{anneal} , then cool slowly.



Heat Treatments


- a) Annealing
- b) Quenching
- c) Tempered Martensite

Adapted from Fig. 10.22, Callister 7e.




Hardenability--Steels

- Ability to form martensite
- Jominy end quench test to measure hardenability.



Adapted from Fig. 11.11, *Callister 7e*. (Fig. 11.11 adapted from A.G. Guy, *Essentials of Materials Science*, McGraw-Hill Book Company, New York, 1978.)


- Hardness versus distance from the quenched end.



Adapted from Fig. 11.12, *Callister 7e*.

Why Hardness Changes W/Position

- The cooling rate varies with position.




Adapted from Fig. 11.13, *Callister 7e*.
(Fig. 11.13 adapted from H. Boyer (Ed.)
*Atlas of Isothermal Transformation and
Cooling Transformation Diagrams*,
American Society for Metals, 1977, p.
376.)




Hardenability vs Alloy Composition

- Jominy end quench results, $C = 0.4 \text{ wt\% C}$

Adapted from Fig. 11.14, *Callister 7e*.
(Fig. 11.14 adapted from figure furnished courtesy Republic Steel Corporation.)



- "Alloy Steels"
(4140, 4340, 5140, 8640)
--contain Ni, Cr, Mo
(0.2 to 2wt%)
--these elements shift the "nose".
--martensite is easier to form.



Quenching Medium & Geometry


- Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

- Effect of geometry:


When surface-to-volume ratio increases:

- cooling rate increases
- hardness increases




Precipitation Hardening

- Particles impede dislocations.
- Ex: Al-Cu system
- Procedure:
 - Pt A: solution heat treat (get α solid solution)
 - Pt B: quench to room temp.
 - Pt C: reheat to nucleate small θ crystals within α crystals.



- Other precipitation systems:

- Cu-Be
- Cu-Sn
- Mg-Al





Adapted from Fig. 11.22, Callister 7e.



Precipitate Effect on TS , $\%EL$

- 2014 Al Alloy:
- TS peaks with precipitation time.
- Increasing T accelerates process.
- $\%EL$ reaches minimum with precipitation time.




Metal Alloy Crystal Structure

Alloys

- substitutional alloys
 - can be ordered or disordered
 - disordered solid solution
 - ordered - periodic substitution

example: CuAu FCC



Metal Alloy Crystal Structure


- Interstitial alloys (compounds)
 - one metal much larger than the other
 - smaller metal goes in ordered way into interstitial “holes” in the structure of larger metal
 - Ex: Cementite – Fe_3C




Metal Alloy Crystal Structure

- Consider FCC structure --- what types of holes are there?

Octahedron - octahedral site = O_H



Tetrahedron - tetrahedral site = T_D




Metal Alloy Crystal Structure


- Interstitials such as H, N, B, C
- FCC has 4 atoms per unit cell

4 O_H sites


8 T_D sites



metal atoms



O_H sites



T_D sites



Summary

- Steels: increase TS , Hardness (and cost) by adding
 - C (low alloy steels)
 - Cr, V, Ni, Mo, W (high alloy steels)
 - ductility usually decreases w/additions.
- Non-ferrous:
 - Cu, Al, Ti, Mg, Refractory, and noble metals.
- Fabrication techniques:
 - forming, casting, joining.
- Hardenability
 - increases with alloy content.
- Precipitation hardening
 - effective means to increase strength in Al, Cu, and Mg alloys.



ANNOUNCEMENTS

Reading:

Core Problems:

Self-help Problems:

