

# Metal Cutting, Forming and Drawing

ITCD – 301-001

# Making a die

- Begins with the die designer
- Good dies have lesser repair
- Metric vs. Pound, inch system
- Important guidelines
- Cost associated problems
- Repeatability

# Simple die punching




Figure 8-1. (a) Sectional view of a cutting die for producing round holes; (b) the punch is compressed after making initial contact with the stock (Smith 2001).

# Die cutting operations




Figure 8-2. Section view of a successful hole-cutting operation involving normal clearances. Note that both the cut edge and slug have one third of metal thickness as a sheared edge shear and two thirds fracture (Smith 1994).

# Die cutting operations

- Controlled by process of plastic deformation
- Fracture
- Tensile and compressive strains included
- Elastic, plastic and fracture
- Fracture through cleavage planes in the reduced area
- Shearing process

# Clearance

- Space left between the punch and die
- No strict rules governing clearance
- Expressed as a percentage of stock thickness per side
- For mild steel, between 5-12 %
- Optimizing die clearance is a good strategy
- Lower cutting pressure
- Extended tool life
- Limiting factors – amount of taper permitted in the hole and allowable burr height

# Insufficient clearance




Figure 8-3. Cutting (a) with *insufficient clearance*. As fracture continues (b), rough tearing occurs and the fracture paths will not meet.

# Insufficient clearance




Figure 8-4. *Insufficient clearance (a) results in a double fracture or breakage condition. Appearance of a cut edge with a double-breakage condition (b).*



# Clearance facts

Tight clearances in the 3-5% range results in,

- Less taper
- Slug pulling reduced
- High cutting forces
- Double breakage problems in thick materials

Large clearances in the 7-25% range results in,

- Longer life for die and punch
- A means to protect against slug pulling
- Low cutting forces
- No double breakage
- Great edge taper and more burr height

# Double breakage solution




Figure 8-5. Start of punch penetration and fracture (a) with a relatively large punch-to-die clearance. The fracture paths (b) will meet evenly.

# Double breakage solutions

- Increase the punch-to-die clearance
- Make the punch smaller
- Increase in taper of the fracture
- Reduction of the cutting force
- Efficiency goes up as less tool sharpening is required
- Clearance of 12-15% per side for soft steels
- Clearance of 25% per side for thick blanks
- Too much clearance is not good either as higher forces are required
- High lateral forces results that lower tool life

# Generous punch-to-die clearance




Figure 8-6. Completion of punch penetration and fracture (a) with a generous punch-to-die clearance. View of a cut edge (b) with large punch-to-die clearances.

# Clearance for irregular shaped blanks




Figure 8-7. How to apply clearances to irregularly shaped holes (Paquin 1962).

# Center of pressure

- For irregularly shaped contours
- Balance the shearing forces on both sides of the ram
- If unbalanced, result is bending moment in the ram
- Undesirable deflections and misalignment
- Find a point about which summation of shear forces are symmetrical
- This point is the center of pressure
- Essentially the center of gravity of the line that is the perimeter of the blank
- Not the center of gravity of the area
- Calculations required to find the center of pressure

# Parameters

- Forces – Lesser than tensile force required (shear strength is 60-80% of tensile strength), shear strength increases with faster strain rate
- Length of cut, material thickness and shear strength
- Theoretical peak cutting force,  $F_s = L \cdot t \cdot S_s$
- Stripping forces,  $F = L \cdot T \cdot 1.5$ ,  $F = L \cdot T \cdot 20,600$  (metric)
- Press tonnage – sum of all the forces required to cut and form the part (cutting, stripping and miscellaneous)
- Lateral and side-thrust forces

# Forces





Figure 8-9. (a) Shear, tensile, and compressive forces occur during the cutting process; (b) as punch-to-die clearance increases, the lateral force, or the side thrust, rapidly increases; (c) as side thrust increases, the cutting clearance may increase, leading to greater side thrust or lateral forces, and potential tool failure.



## Reducing cutting forces

- High forces exerted for a short period
- Spread the force over a longer period of press stroke
- By adjusting the punch height so they differ in length by  $\frac{1}{3}$ 'rd the material thickness and cut in sequence
- Add shear to the die or punch equal to  $\frac{1}{3}$ 'rd the material thickness – tonnage reduced by 50%

# Cutting force reduction



# Bending




Figure 8-15. A metal beam supported at two points, with a load applied at the midpoint, resulting in bending or deflection.




Figure 8-16. If the applied force does not exceed the material-yield strength, the beam returns to its undeflected shape.

# Bending




Figure 8-17. Simple beam deflection occurs in air bending. If the applied force exceeds the material-yield strength, the beam retains a permanent set or bend when the load is removed.




Figure 8-18. Springback occurs until the residual stress forces are balanced by the stiffness of the material.

## Factors affecting Springback

- Higher material strength
- Thinner material
- Lower E
- Larger die radius
- Greater clearance
- Flatter part-surface contour
- Less irregularity in part outline

# Air bending and Coining




Figure 8-19. Simple tooling of the type used to air-bend sheet-metal parts in press brakes. The upper die is lowered a little and a hit is made until the desired bend angle is obtained.




Figure 8-20. Coining the bend requires high tonnage to obtain a sharp, accurate bend.

# Wipe flanging




Figure 8-21. Sectional view of a wipe-flanging die.




Figure 8-22. Close-up view of the point of flange steel contact on the bend radius in a wipe-flanging die.



# Wipe flanging




Figure 8-23. The side of the radius is coined and a relief angle is provided in the lower-die steel in this improved springback control method.



# Rotary action die bending




Figure 8-24. A Ready™ bender makes initial contact with the stock. As the die closes, the bender clamps and bends the stock. (Courtesy Ready Tools, Inc.)




Figure 8-25. A Ready™ bender bends the stock through rotary action of the circular member. (Courtesy Ready Tools, Inc.)

# Rotary action die bending




Figure 8-26. A Ready™ bender overbends the stock at the bottom of the stroke to provide for springback. (Courtesy Ready Tools, Inc.)

# Forming




Figure 8-27. A set of forming blocks used without a die set.

# Forming

- Large % of stampings
- Both simple and complicated
- Plastic flow
- Localized plastic flow
- Forming dies
- Number of stampings required
- Solid forming dies
- Coining dies

# Radii considerations




Figure 8-30. Radii considerations for form die design.




Figure 8-31. Rubber or polyurethane forming die and punch

# Beading and curling




Figure 8-32. *Starting curl radius.*




Figure 8-33. *Curling punch design.*

# Beading and Curling




Figure 8-34. *Curling die design.*



# Deep Drawing of cups




Figure 8-48. A simple drawing die.



# Draw dies




Figure 8-50. Draw dies: (a) simple type; (b) simple draw die for heavy stock.

# Draw dies




Figure 8-51. Draw die with spring pressure pad.




Figure 8-52. A draw die with spring pressure pad and stripper.

# Inverted draw die




Figure 8-53. Cross section of an inverted draw die for a single-ram press; die is attached to the ram; punch and pressure are on the lower shoe.

# References

- Fundamentals of tool design, fifth edition, Society of Manufacturing Engineers
- Donaldson, and Lecain, Tool Design, McGraw Hill



Questions?